



3933 US Route 11  
Cortland, NY. 13045

Telephone: 607-758-6291  
Facsimile: 607758-6661  
www.intertek-etlsemko.com

February 02, 2012

Mr. Patrick Sullivan  
Amstep Products  
190 Century Drive  
Bristol, CT 06010

pjsjr@amstep.com

Intertek Test Report: 100634407CRT-001T

Dear Mr. Sullivan,

Intertek has completed Visibility testing of the Photoluminescent Stair tread, model: Retrofit 300, to the indicated requirements of UL Safety Standard for Luminous Egress Path Marking Systems, UL 1994, 3rd Ed, dated Jan. 03, 2004, rev through November 9, 2010. The test samples were received on January 17, 2012 in new condition. The evaluation was performed at Intertek, Cortland, NY, on February 01, 2012. The results of these tests are indicated as follows:

Standard	Clause	Test Completed	Pass / Fail
UL 1994	35	Visibility test	Pass

The Photoluminescent Stair tread, model: Retrofit 300 were found to be in compliance with the indicated requirements of UL Safety Standard for Luminous Egress Path Marking Systems, UL 1994, 3rd Ed, dated Jan. 03, 2004, rev through November 9, 2010. This Test Report concludes the work anticipated for this phase of your project under Intertek quote number 500348702. See attached data for testing details. Any questions can be directed to Aaron Oldweiler at Aaron.Oldweiler@intertek.com.

Reported by

Aaron Oldweiler  
Project Engineer

Reviewed by

Kenneth L. Morgan, Jr.  
Engineering Team Leader



This report is for the exclusive use of Intertek's Client and is provided pursuant to the agreement between Intertek and its Client. Intertek's responsibility and liability are limited to the terms and conditions of the agreement. Intertek assumes no liability to any party, other than to the Client in accordance with the agreement, for any loss, expense or damage occasioned by the use of this report. Only the Client is authorized to copy or distribute this report and then only in its entirety. Any use of the Intertek name or one of its marks for the sale or advertisement of the tested material, product or service must first be approved in writing by Intertek. The observations and test results in this report are relevant only to the sample tested. This report by itself does not imply that the material, product, or service is or has ever been under an Intertek certification program.

**Intertek Testing Services NA, Inc.**

3933 US Route 11, Cortland, NY 13045 USA

Telephone: +1 607-753-6711 Fax: +1 607-756-9891 Web: www.intertek-etlsemko.com

